



WA Clean is the right choice because it makes no difference.

Regardless of whether the environment is light or dark, the WA Clean always remains objective.

For the first time, rate your blasted surface with a measuring device that reliably displays the purity of the surface, regardless of light, reflection, daylight or artificial light.



You will not always find laboratory conditions like in one of our 6 test centers



Using a pre-defined reference level of purity or in true / false mode, the device works reliably and you can document and archive the collected data without software in Excel.



WA Clean is essential when it comes to quality assurance and documentation